



# ROVI JAWS - 5" VISE - MILL PLUNGE METHOD

## STEP 1




[www.home-machine-shop.com](http://www.home-machine-shop.com)




[www.home-machine-shop.com](http://www.home-machine-shop.com)

## STEP 2




[www.home-machine-shop.com](http://www.home-machine-shop.com)




[www.home-machine-shop.com](http://www.home-machine-shop.com)

# ROVI JAWS - 5" VISE - MILL SLOT METHOD

## STEP 1




[www.home-machine-shop.com](http://www.home-machine-shop.com)




[www.home-machine-shop.com](http://www.home-machine-shop.com)

## STEP 2



[www.home-machine-shop.com](http://www.home-machine-shop.com)



[www.home-machine-shop.com](http://www.home-machine-shop.com)